

February 2021 Fire Marshal Report

2/1/2021 Bedroom Fire 1542 Glen Ave. Bedroom Fire caused by candle fire contained to single room. Minor Fire damage moderate smoke damage.

Follow up on 2/5/2021 Residents back at home clean-up of smoke damage by private contractor.

2/6/2021 Controlled burn notification given. 1114 Taylor Drive. As per Borough ordinance all firepits must be located 20 feet from any structure. Resident notified to move firepit to another location other than front patio.

2/20/2021 Oven Fire 1067 Taylor Drive. Grease build up causing small fire contained to oven. Damage to oven. Home Owner notified that oven needed to be replaced.

Follow up on 2/23/2021 Stove unit replaced but upon inspection pipe in basement was leak natural gas. Gas secured to pipe and unit. Until pipes replaced.

Follow up on 2/26/2021 Pipes replaced from valve in basement to valve behind stove and new flex line installed.