

## September 2021 Fire Marshal Report

### **409 Charmont Ave.**

9/4/2021 Follow up visit to verify Fire Alarm system was repaired from False alarm on 9/1/2021

### **701 B2 Ashland Ave.**

9/5/2021 Follow up visit to verify Heat Detector repaired from false alarm on 9/1/2021 System still down owner given 48 hours to have system restored

9/7/2021 Second follow up visit system restored operating as normal.

### **1523 Glen Ave.**

9/10/2021 Follow visit to verify Heating and Hot Water system repaired from CO leak on 9/7/2021. No repair made Home Owner Replaced entire summer winter hook up for heating and hot water.

### **500 Kaiser Drive**

9/11/2021 Letter sent advising Company of false alarm ordinance due to false alarms on 9/8 and 9/9/2021 and that they needed to have Fire alarm system serviced. Next false alarm would result in possible fines.

9/15/2021 Phone call received at Station 1 advising that alarm system was serviced and 2 smoke detector heads replaced.

9/28/2021 False alarm received Alarm company contacted while fire company on scene and service tech was dispatched to service system. No fines issued due to company making attempts to resolve issues with alarm.

No other alarms have been received as of 10/13/2021

### **59 Folcroft Ave**

9/15/2021 Follow up visit from 9/14/2021 Gas Leak to verify flex hose behind stove had been replaced. Repairs were made and PECO had restored gas service to stove.

**701 B Ashland Ave.**

9/27/2021 Visited business to verify proper handling of oil soaked rags that caused fire in truck trailer on 9/20/2021. Fire proof containers were installed at loading dock doors for proper storage of contaminated rags.

**521 Garfield Ave**

9/27/2021 Follow up visit from 9/21/2021 to verify CO alarm had been replaced new combination detectors installed on all 3 floors.

**887 Taylor Drive.**

9/29/2021 Follow up visit to verify CO alarm replaced not replaced as of date.

10/5/2021 second follow up alarms replaced and operating as designed